CNRH/JBPHH TRAFFIC SAFETY COUNCIL HAZARD ABATEMENT LOG

ISSUE	DATE / BRIEF DESCRIPTION	CORRECTIVE ACTION / CA POC	DATE CA TAKEN	REMARKS / COMMENTS	СО\$Т	RAC#	STATUS & DATE
	6 MAY 2010: Replace 3 yield signs w/ stop signs @ Moffet St. and Luke Dr. to eliminate confusion as to who has the right of way. (Hickam)					4	OPEN
		Action: Mr. Fujioka, CNRH Traffic Safety Engineer: Conduct Assessment.	5/13/2010	Recommend replace (3) YIELD signs w/ (3) STOP signs to include painting (3) stop lines/bars.			
		Action: Mr. Bertubin - Request submitted to CE to replace signs and to paint stop lines.	10/27/2010	WR under CE Work Induction Board (WIB) review for action.	Pending material & labor cost from CE.		
	6 MAY 2010: Repair road surface & sidewalk in front of tennis courts between Signer/Fox Blvd & 11 th Street. (Hickam)	Submit work order to NAVFAC to have sidewalk repaired.				5	OPEN
		Action: Mr. Bertubin - Work request submitted as requested and/or directed.	10/27/2010	WR submitted; under CE Work Induction Board (WIB) review & action.	Pending material & labor cost from CE.		Awaiting CE/WIB response
3	6 MAY 2010: Heavy traffic @ Hangar Avenue and "G" Street poses hazard to pedestrians. (Hickam)	Evaluate traffic concern at subject location and determine if intersection requires 4-way stop. Submit WR as required or needed.		29 Oct 2010. JBPHH TSC recommended that STOP signs be installed.		3	OPEN
		Action : Mr. Fujioka (TS Engr): Assess, verify, and recommend CA as required and/or needed.	5/13/2010	4-way stop not req'd; recommend painting "STOP" on G St. in front of stop lines; add crosswalk on Hangar Avenue.			
		Action: Mr. Bertubin - Submit WR accordingly.		·	Pending material & labor cost from CE.		Awaiting CE/WIB response
	6 MAY 2010: There is a need to install stop signs in the Air Mobility Command (AMC) passenger terminal parking lot. (Hickam) Initially reported on Air Force 457 Hazard Rpt submitted 4/6/10.	Evaluate subject parking lot and determine if stop signs are req'd to augment existing stop lines on pavement.				4	OPEN
		Action: Mr. Fujioka - Assess, verify, and recommend CA as required and/or needed.		Evaluation concluded that stop lines were sufficient to control vehicular traffic.			
		Action : Mr. Kantorowicz - Follow-up if recommended action(s) effective.	7/23/2010	Control of vehicular traffic an enforcement issue; GSM recommends Base Security enforce traffic movement in area.			
		Action: Mr. Bertubin - Submit WR accordingly.	27-Oct-10	WR submitted; under CE/WIB review.	Pending material & labor cost from CE.		Awaiting CE/WIB response
	6 MAY 2010: Stop signs at Bouquet and Signer Blvds do not have retro-reflective mat'l.	Contact Mr. Tripp (HCH) to request replacement signs.					CLOSED
		Action: Mr. Kantorowicz - Follow-up & confirm closure. Action: Mr. Tripp	7/23/2010	Stop signs replaced.			
		Action: IVII. TTIPP	0/10/2010	отор зідпо геріасец.			
6	6 MAY 2010: H1 and H2 traffic merge and speeding issues outside of Hickam main gate.	Coordinate evaluation with HPD to determine corrective action(s).		Addressed during JB Safety Stand-down conducted on 17 Jun 2010.			CLOSED
		Action: Mr. Fujioka	5/21/2010				
7	6 MAY 2010: Replace crosswalk yield signs with crosswalk stop signs at Hickam side of JBPHH.	Order six (6) new crosswalk stop signs to replace yield signs as required by state law.			Estmated Cost per sign \$390.00	5	OPEN
		Action: Mr. Kamanao-Submit purchase request to NAVFAC.	5/7/2010	Per NAVFAC, funding to purchase these signs are not available. Approximate cost of material is \$390/sign.			

CNRH/JBPHH TRAFFIC SAFETY COUNCIL HAZARD ABATEMENT LOG

		Action: Mr. Bertubin - Submit WR to purchase and install crosswalk stop signs for JB-Hickam.		Purchase & installation WR submitted to JB- Hickam CE; WR under CE WIB review.	Pending material & labor cost from CE.		Awaiting CE/WIB response
8	6 MAY 2010: Speeding on O'Malley Blvd.	Place add'l speed detector/radar signs along O'Malley Blvd.		Addressed during JBPHH TSC meeting of 29 Oct 2010.		4	OPEN
		Action: MSgt Della Rosa - Follow-up on locations for installment.			Awaiting info from CA POC		
9	6 MAY 2010: Faded crosswalk and pavement markings on JBPHH.	Survey and identify crosswalks and pavement marking requiring repainting. Submit work request to NAVFAC for action.				5	OPEN
		Action: Mr. Fujioka - Survey action required/requested. Action: Mr. Bertubin - Submit WR for JB-Hickam as required and as recommended .	10/27/2010	Survey of JB-Hickam WR submitted; under CE WIB for review.	Awaiting response from CE WIB		
10	6 MAY 2010: Insufficient number of speed limit signs on JBPHH.	Review/determine max speed limit for JBPHH; submit WR to purchase & install signs.		Under review by Capt Kitchens; CNIC Inst 5560.1 requires 25 mph max.		5	OPEN
		Action : Mr. Fujioka - Assess & determine number of signs required.	6/18/2010	Purchase of signs pending upon decision on max speed limit onboard JBPHH.			
		Action: Mr. Bertubin - Submit WR for TS Engr to determine amount, purchase & installation for JB-Hickam.	10/27/2010	Survey, purchase & installation WR for JB- Hickam submitted; under CE/WIB review.	Pending material & labor cost from CE.		Awaiting CE/WIB response
11	6 MAY 2010: Lima Landing (West Lock) - Vehicle operators cannot see pedestrian traffic due to inadequate lighting.	Review and evaluate location to determine appropriate corrective action.					OPEN
		Action: Mr. Fujioka - Coordinate w/ WEST Lock Installation Traffic Coordinator(s) for CA.	5/24/2010	Initial coordination done; interim CA ongoing; WR pending submission.			
12	6 MAY 2010: Midway Drive (NCTAMS) - Geography (gully) with limited walkways and lighting create hazardous conditions to pedestrians.	Review and evaluate location to determine appropriate corrective action.			MilCon Project estimated @ \$25M with an ECD in FY- 2015		OPEN
		Action: Mr. Fujioka - Coordinate and initiate CA	5/5/2010	Discussed with Mr. Young, NAVFAC Engr. Funding cost for MilCon approved for \$25M with an ECD in FY-2015.			Interim CA by NAVFAC & NCTAM CO.
13	6 MAY 2010: Traffic rules and regs need to be consolidated for JBPHH.	Review and develop JBPHH traffic instruction for publication and dissemination.		29 Oct 2010; Regs/policy under review by Capt Kitchens. JBPHH TSC for action.		3	OPEN